

Echoflex Solutions Release Note

MOS-DT Ceiling-Mount Occ/Vac Sensor

Product Line:	MOS-DT Ceiling-Mount Occ/Vac Sensor
Description:	Version 1.3.0 Firmware
Effective Date:	2021-05-20

Purpose

The purpose of this release is to correct a firmware defect that caused the sensor to ignore any changes made by an operator to the sensor's PIR or audio sensitivity, or the internal occupancy timer. For any questions relating to the contents of this release or the behavior of this firmware, please contact Echoflex Solutions using the information at the bottom of this page.

Defect Description

The defect found in v1.2.9 firmware meant that if an operator attempted to adjust the PIR sensitivity, audio sensitivity, or sensor occupancy timer value, the changes would not get saved when exiting the setting menu.

Availability

Firmware v1.3.0 is currently available in new sensors. Field upgrade of the firmware is not available. If you have a sensor presenting the reported defect condition, please contact Echoflex Solutions Technical Support for a replacement unit.

Documentation

Please keep this release note with your MOS-DT Ceiling-Mount Occ/Vac Sensor Installation Guide for descriptions of the newest features, changes, and bug fixes. Manuals are in portable document format (pdf) and are available for download at echoflexsolutions.com.

Compatibility

This release is compatible with the following Echoflex Solutions hardware:

- MOS-DT-UA
- MOS-DT-UB

Issue Corrected in v1.3.0

The firmware was adjusted so any changes made in the sensors input sensitivity menu were saved when exiting.